

TEST REPORT

KOREA ENVIRONMENTAL AND WATER WORKS INSTITUTE
ZIP)07201 YEONGPYUNGRO 28SAGIL 29, SEOUL, KOREA
TEL : 02-2637-1234 FAX : 02-2631-8767

TEST REPORT NO. : IL-180147
PAGE (1) / (Total 1) END.



1. Request client
Request Company : CLEARWIN
Company Address : Mokdong Dongro 293, Hyundai41 Tower 804, Yangchun-Gu, Seoul, Korea
2. Test list / material / sample explanation : Before Installation
3. Test purpose : Quality management
4. Test period : 2018. 2. 5. ~ 2. 13.
5. Test method : The quality of water test standard
6. Test environment : Humidity : (27 ± 5) & R.H.
7. Test result

Test item	Unit	NO. 2		NO. 1		Remark
		Down line (Left side)	Down line (Right side)	Up line (Left side)	Up line (Right side)	
General Bacteria 一般細菌	CFU/mL	6.0×10^5	9.4×10^5	4.7×10^4	4.8×10^5	-
Total Coliform 大腸菌	-/100 mL	non-detection	Detection	Detection	non-detection	-
Fecal Streptococci 糞便性鏈球菌	-/250 mL	non-detection	non-detection	non-detection	non-detection	-
Pseudomonas Aeruginosa 綠膿桿菌	-/250 mL	non-detection	non-detection	non-detection	non-detection	-
Sporeforming Sulfite Reducing Anaerobes	-/50 mL	non-detection	non-detection	non-detection	non-detection	-
Salmonella 鼠狀芽菌桿菌 沙門氏菌	-/250 mL	non-detection	non-detection	non-detection	non-detection	-
Shigella 志賀氏菌屬 (痢疾桿菌)	-/250 mL	non-detection	non-detection	non-detection	non-detection	-

Confirmation	Tester	Kang Sung-mo	Technical Supervisor	Song Min-hyung
--------------	--------	--------------	----------------------	----------------

1. This test report is tested result by sample what request client's sample. So, this is not certified all of product quality.
2. This test report is only for reference. So, It can not be used for every promotion, advertisement and lawsuit. And It can not be possible that reissue without approval in writing.

2018. 2. 13.

Chief of KOREA ENVIRONMENTAL AND WATER WORKS INSTITUTE



TEST REPORT

KOREA ENVIRONMENTAL AND WATER WORKS INSTITUTE
ZIP)07201 YEONGPYUNGRO 28SAGIL 29, SEOUL, KOREA
TEL : 02-2637-1234 FAX : 02-2631-8767

TEST REPORT NO. : IL-180147
PAGE (1) / (Total 6) END.



1. Request client

Request Company : CLEARWIN

Company Address : Mokdong Dongro 293, Hyundai41Tower 804, Yangchun-Gu, Seoul, Korea

2. Test list / material / sample explanation : Before Installation

3. Test purpose : Quality management



4. Test period : 2018. 2. 5. ~ 2. 13.

5. Test method : The quality of water test standard

6. Test environment : Humidity : (27 ± 5) & R.H.

7. Test result

Test item	Unit	NO. 2		NO. 1		Remark
		Down line (Left side)	Down line (Right side)	Up line (Left side)	Up line (Right side)	
General Bacteria	CFU/mL	6.0×10^5	9.4×10^5	4.7×10^4	4.8×10^5	-
Total Coliform	-/100 mL	non-detection	non-detection	non-detection	non-detection	-
Fecal Streptococci	-/250 mL	non-detection	non-detection	non-detection	non-detection	-
Pseudomonas Aeruginosa	-/250 mL	non-detection	non-detection	non-detection	non-detection	-
Sporeforming Sulfite Reducing Anaerobes	-/50 mL	non-detection	non-detection	non-detection	non-detection	-
Salmonella	-/250 mL	non-detection	non-detection	non-detection	non-detection	-
Shigella	-/250 mL	non-detection	non-detection	non-detection	non-detection	-

Confirmation	Tester	Kang Sung-mo 	Technical Supervisor	Song Min-hyung 
--------------	--------	--	----------------------	--

1. This test report is tested result by sample what request client's sample. So, this is not certified all of product quality.

2. This test report is only for reference. So, It can not be used for every promotion, advertisement and lawsuit.
And It can not be possible that reissue without approval in writing.

2018. 2. 13.

Chief of KOREA ENVIRONMENTAL AND WATER WORKS INSTITUTE




TEST REPORT

KOREA ENVIRONMENTAL AND WATER WORKS INSTITUTE
ZIP)07201 YEONGPYUNGRO 28SAGIL 29, SEOUL, KOREA
TEL: 02-2637-1234 FAX: 02-2631-8767




7. Test result



General Bacteria (Before Installation)



Total Coliform (Before Installation)



General Bacteria (After Installation)



Total Coliform (After Installation)